

## LFR-FSW - Bug #553

### NON CONFORMITE SSS-CP-EQS-326

23/10/2015 12:12 PM - bruno katra

<b>Status:</b>	Closed	<b>Start date:</b>	23/10/2015
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	bruno katra	<b>% Done:</b>	100%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>revision:</b>	r0		

#### Description

Also tracked in <https://jira-lesia.obspm.fr/browse/RPWSWR-624>

Upon reception of a TC\_XXX\_ENTER\_MODE(SBM1) / TC\_XXX\_ENTER\_MODE(SBM2) / TC\_XXX\_ENTER\_MODE(NORMAL), the equipment flight software shall not re-initialize the NORMAL data flow if this one was already active.

**ATTENTION NOUS NE SERONS JAMAIS CONFORMES (Paul)++**

#### History

**#1 - 04/12/2015 04:47 PM - bruno katra**

- Description updated

**#2 - 20/01/2016 11:31 AM - paul leroy**

- Assignee changed from paul leroy to bruno katra

Modification de la commutation des modes effectuée pour la révision 3.0.0.13.

**#3 - 02/03/2016 03:16 PM - bruno katra**

- % Done changed from 0 to 60

A partir de 3.0.0.20 : les produits WF ne redémarrent pas mais les produits spectraux redémarrent (ASM + BP)

**#4 - 24/05/2016 11:43 PM - bruno katra**

- Status changed from New to Closed

- % Done changed from 60 to 100

RFD 227 émise et acceptée pour DP R3 updated