

INSTRU - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated |
|------|---------|---------|----------|---|-------------------------|---------------------|
| 3914 | Support | Stalled | Normal | Question sur la dernière matrice des KCOEFF... | Alexis Jeandet | 08/12/2021 01:29 PM |
| 990 | Support | Closed | Normal | TC_LFR_LOAD_FILTER_PAR bugs | bruno katra | 22/03/2017 02:51 PM |
| 979 | Support | Closed | Normal | Mise à jour SRS et SVS et UM | bruno katra | 22/06/2018 05:15 PM |
| 956 | Support | Closed | High | Documenter le mecanisme associé à SSS-CP-EQS-526 | Alexis Jeandet | 01/04/2019 12:03 PM |
| 868 | Support | Closed | High | Question sur merge_fbins_masks | bruno katra | 22/03/2017 02:57 PM |
| 721 | Support | Closed | Low | improvements in QCdf | Alexis Jeandet | 01/07/2016 11:12 AM |
| 714 | Support | Stalled | Normal | Parametrage TCP | Alexis Jeandet | 22/03/2021 12:09 PM |
| 706 | Support | Closed | Normal | Pb aux bornes des intervalles pour le rejet des fréquences polluées par les roues inertielles | Gerald Saule | 22/06/2018 05:22 PM |
| 656 | Support | Closed | Normal | SHow to validate HK_LFR_VHDL_SM field | Veronique bouzid | 21/06/2018 01:27 PM |
| 634 | Support | Closed | Urgent | SEction HK_LFR_STATUS_WORD in TM_LFR_HK | paul leroy | 26/02/2016 11:35 AM |
| 627 | Support | Closed | Urgent | Commutation immediate | Veronique bouzid | 27/01/2017 02:36 PM |
| 626 | Support | Closed | Low | Lost TM_LFR_HK in 3.0.0.22 | bruno katra | 17/02/2016 01:42 PM |
| 607 | Support | Closed | Normal | medium Criticity : How can we do it | Veronique bouzid | 18/01/2017 12:26 PM |
| 596 | Support | Stalled | Normal | Mise à jour logiciel LFR-SGSE | Alexis Jeandet | 22/03/2021 12:10 PM |
| 589 | Support | Closed | Normal | TC_LFR_LOAD_FBINS_MASK | Veronique bouzid | 03/03/2016 04:51 PM |
| 561 | Support | Closed | Normal | Modifier le masque utilisé pour lire le time-code valide | Veronique bouzid | 22/02/2016 02:53 PM |
| 545 | Support | Closed | Normal | Send TIMECODE without TC_LFR_UPDATE_TIME after SYNCHRONISATION | paul leroy | 02/11/2015 11:18 AM |
| 537 | Support | Closed | Urgent | requirement SSS-CP-EQS-522 et SSS-CP-EQS-523 | Veronique bouzid | 15/10/2015 12:57 PM |
| 473 | Support | Closed | Normal | R3 *** Adapter les scripts aux exigences | Veronique bouzid | 27/01/2017 02:41 PM |
| 399 | Support | Closed | Normal | Mode Standby durant 3s à la fin des tests | Veronique bouzid | 01/10/2015 01:16 PM |
| 258 | Support | Closed | Normal | Numéro de version du code VHDL | Jean-Christophe Pellion | 10/02/2015 04:27 PM |
| 181 | Support | Closed | High | Impossibilité de provoquer un TM_LFR_EXE_ERROR | paul leroy | 02/03/2016 02:44 PM |