

INSTRU - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
718	Support	New	Normal	QCdf should standardize extracted Time	Alexis Jeandet	14/02/2019 10:29 AM
872	Support	New	Normal	Comportement lorsque l'on ne masque que 2 bins // Reaction Wheel	thomas chust	30/12/2016 04:32 PM
688	Support	Resolved	High	No way to add a colorbar into an axis object in qtcharts		14/02/2019 10:29 AM
4075	Support	Resolved	Normal	Obtain good result in the comparison of Reference/IDL/python waveforms		26/04/2023 04:24 PM
4082	Support	Resolved	Normal	Find why the computed spectrum is very different of ref, only for antenna y and z, probably a bug	Theo Stassen	05/05/2023 06:32 PM
4084	Support	Resolved	Normal	Investigate why results are in general better for antenna x than y and z	Theo Stassen	05/05/2023 06:37 PM
4197	Support	Resolved	Normal	Research with laurent about the difference of code results and experimentations	Theo Stassen	17/10/2023 04:50 PM
4207	Support	Resolved	Normal	New tries concerning the differences between python and matlab results	Theo Stassen	27/10/2023 05:43 PM
486	Support	Feedback	Urgent	SSS-CP-FS-340 : Design or Test	bruno katra	02/10/2015 07:42 AM
494	Support	Feedback	Normal	Gestion timecode	Veronique bouzid	18/09/2015 02:01 PM
1090	Support	Feedback	Normal	Back to time management	Veronique bouzid	28/04/2017 01:24 PM
1091	Support	Feedback	Normal	Lost some BP packets in BURST mode	Veronique bouzid	28/04/2017 01:33 PM
181	Support	Closed	High	Impossibilité de provoquer un TM_LFR_EXE_ERROR	paul lero	02/03/2016 02:44 PM
258	Support	Closed	Normal	Numéro de version du code VHDL	Jean-Christophe Pellion	10/02/2015 04:27 PM
399	Support	Closed	Normal	Mode Standby durant 3s à la fin des tests	Veronique bouzid	01/10/2015 01:16 PM
473	Support	Closed	Normal	R3 *** Adapter les scripts aux exigences	Veronique bouzid	27/01/2017 02:41 PM
537	Support	Closed	Urgent	requirement SSS-CP-EQS-522 et SSS-CP-EQS-523	Veronique bouzid	15/10/2015 12:57 PM
545	Support	Closed	Normal	Send TIMECODE without TC_LFR_UPDATE_TIME after SYNCHRONISATION	paul lero	02/11/2015 11:18 AM
561	Support	Closed	Normal	Modifier le masque utilisé pour lire le time-code valide	Veronique bouzid	22/02/2016 02:53 PM
589	Support	Closed	Normal	TC_LFR_LOAD_FBINS_MASK	Veronique bouzid	03/03/2016 04:51 PM
607	Support	Closed	Normal	medium Criticity : How can we do it	Veronique bouzid	18/01/2017 12:26 PM
626	Support	Closed	Low	Lost TM_LFR_HK in 3.0.0.22	bruno katra	17/02/2016 01:42 PM
627	Support	Closed	Urgent	Commutation immediate	Veronique bouzid	27/01/2017 02:36 PM
634	Support	Closed	Urgent	SAction HK_LFR_STATUS_WORD in TM_LFR_HK	paul lero	26/02/2016 11:35 AM
656	Support	Closed	Normal	SHow to validate HK_LFR_VHDL_SM field	Veronique bouzid	21/06/2018 01:27 PM
706	Support	Closed	Normal	Pb aux bornes des intervalles pour le rejet des fréquences polluées par les roues inertielles	Gerald Saule	22/06/2018 05:22 PM
721	Support	Closed	Low	improvements in QCdf	Alexis Jeandet	01/07/2016 11:12 AM
868	Support	Closed	High	Question sur merge_fbins_masks	bruno katra	22/03/2017 02:57 PM
956	Support	Closed	High	Documenter le mecanisme associé à SSS-CP-EQS-526	Alexis Jeandet	01/04/2019 12:03 PM
979	Support	Closed	Normal	Mise à jour SRS et SVS et UM	bruno katra	22/06/2018 05:15 PM
990	Support	Closed	Normal	TC_LFR_LOAD_FILTER_PAR bugs	bruno katra	22/03/2017 02:51 PM

#	Tracker	Status	Priority	Subject	Assignee	Updated
596	Support	Stalled	Normal	Mise à jour logiciel LFR-SGSE	Alexis Jeandet	22/03/2021 12:10 PM
714	Support	Stalled	Normal	Parametrage TCP	Alexis Jeandet	22/03/2021 12:09 PM
3914	Support	Stalled	Normal	Question sur la dernière matrice des KCOEFF...	Alexis Jeandet	08/12/2021 01:29 PM