

## LFR-FSW - Issues

| #    | Tracker | Status   | Priority | Subject   | Assignee         | Updated             |
|------|---------|----------|----------|---|------------------|---------------------|
| 626  | Support | Closed   | Low      | Lost TM_LFR_HK in 3.0.0.22  | bruno katra      | 17/02/2016 01:42 PM |
| 3914 | Support | Stalled  | Normal   | Question sur la dernière matrice des KCOEFF...  | Alexis Jeandet   | 08/12/2021 01:29 PM |
| 1091 | Support | Feedback | Normal   | Lost some BP packets in BURST mode  | Veronique bouzid | 28/04/2017 01:33 PM |
| 1090 | Support | Feedback | Normal   | Back to time management   | Veronique bouzid | 28/04/2017 01:24 PM |
| 990  | Support | Closed   | Normal   | TC_LFR_LOAD_FILTER_PAR bugs   | bruno katra      | 22/03/2017 02:51 PM |
| 979  | Support | Closed   | Normal   | Mise à jour SRS et SVS et UM  | bruno katra      | 22/06/2018 05:15 PM |
| 714  | Support | Stalled  | Normal   | Parametrage TCP   | Alexis Jeandet   | 22/03/2021 12:09 PM |
| 706  | Support | Closed   | Normal   | Pb aux bornes des intervalles pour le rejet des fréquences polluées par les roues inertielles | Gerald Saule     | 22/06/2018 05:22 PM |
| 656  | Support | Closed   | Normal   | SHow to validate HK_LFR_VHDL_SM field   | Veronique bouzid | 21/06/2018 01:27 PM |
| 607  | Support | Closed   | Normal   | medium Criticity : How can we do it   | Veronique bouzid | 18/01/2017 12:26 PM |
| 596  | Support | Stalled  | Normal   | Mise à jour logiciel LFR-SGSE   | Alexis Jeandet   | 22/03/2021 12:10 PM |
| 589  | Support | Closed   | Normal   | TC_LFR_LOAD_FBINS_MASK  | Veronique bouzid | 03/03/2016 04:51 PM |
| 561  | Support | Closed   | Normal   | Modifier le masque utilisé pour lire le time-code valide                                      | Veronique bouzid | 22/02/2016 02:53 PM |
| 545  | Support | Closed   | Normal   | Send TIMECODE without TC_LFR_UPDATE_TIME after SYNCHRONISATION                                | paul leroy       | 02/11/2015 11:18 AM |
| 494  | Support | Feedback | Normal   | Gestion timecode  | Veronique bouzid | 18/09/2015 02:01 PM |
| 473  | Support | Closed   | Normal   | R3 *** Adapter les scripts aux exigences  | Veronique bouzid | 27/01/2017 02:41 PM |
| 399  | Support | Closed   | Normal   | Mode Standby durant 3s à la fin des tests   | Veronique bouzid | 01/10/2015 01:16 PM |
| 956  | Support | Closed   | High     | Documenter le mecanisme associé à SSS-CP-EQS-526  | Alexis Jeandet   | 01/04/2019 12:03 PM |
| 868  | Support | Closed   | High     | Question sur merge_fbins_masks  | bruno katra      | 22/03/2017 02:57 PM |
| 181  | Support | Closed   | High     | Impossibilité de provoquer un TM_LFR_EXE_ERROR  | paul leroy       | 02/03/2016 02:44 PM |
| 634  | Support | Closed   | Urgent   | SSection HK_LFR_STATUS_WORD in TM_LFR_HK  | paul leroy       | 26/02/2016 11:35 AM |
| 627  | Support | Closed   | Urgent   | Commutation immediate   | Veronique bouzid | 27/01/2017 02:36 PM |
| 537  | Support | Closed   | Urgent   | requirement SSS-CP-EQS-522 et SSS-CP-EQS-523  | Veronique bouzid | 15/10/2015 12:57 PM |
| 486  | Support | Feedback | Urgent   | SSS-CP-FS-340 : Design or Test  | bruno katra      | 02/10/2015 07:42 AM |