

## Solar Orbiter LFR - Issues

| #    | Tracker | Status   | Priority  | Subject   | Assignee                | Updated             |
|------|---------|----------|-----------|---|-------------------------|---------------------|
| 1378 | Task    | New      | Immediate | Test LFR boot Vs Temperature Vs sub_1V5 voltage | Alexis Jeandet          | 12/05/2017 04:29 PM |
| 471  | Bug     | New      | High      | Bistream 1.1.85 issues                          |                         | 22/06/2018 05:08 PM |
| 470  | Bug     | Resolved | High      | Bistream 1.1.85 snapshots non générés           | Jean-Christophe Pellion | 19/07/2015 03:00 PM |