

INCLINE - ICP - Task #3421

Repair CI2 mass flow controller

19/09/2019 11:40 AM - Garrett Curley

Status:	New	Start date:	19/09/2019
Priority:	Normal	Due date:	28/11/2019
Assignee:	Garrett Curley	% Done:	0%
Category:		Estimated time:	0.50 hour
Target version:		Spent time:	0.00 hour
revision:	r0		
Description			
Defective Brooks Model 5850TR			

History

#1 - 19/09/2019 01:02 PM - Garrett Curley

- File Fiche de retour SAV - 4.docx added

- Estimated time set to 0.50 h

Subject: RE: reparation 5850TR
Date: Thu, 19 Sep 2019 11:31:42 +0200
From: sebastien.briere@servinstrumentation.fr
To: 'Jean-paul Booth' <jean-paul.booth@lpp.polytechnique.fr>

Bonjour M. BOOTH,
Etant à CentraleSupélec demain, je peux vous proposer de venir passer prendre votre appareil.
Veuillez trouver ci-jointe la fiche de retour SAV à remplir préalablement et joindre avec le régulateur défectueux.
Auriez-vous une disponibilité demain ?
Cordialement
Sébastien Brière | Ingénieur Commercial | : sebastien.briere@servinstrumentation.fr |

Files

Fiche de retour SAV - 4.docx	35.6 KB	19/09/2019	Garrett Curley
------------------------------	---------	------------	----------------