LFR-FSW - Bug #565

[QR R3] [JIRA] (RPWSWR-577) Quality remark on Software Validation Report

19/11/2015 05:01 PM - bruno katra

Status: Closed Start date: 19/11/2015 **Priority:** High Due date: Assignee: bruno katra % Done: 100% Category: **Estimated time:** 0.00 hour Target version: Spent time: 0.00 hour revision: r0

Description

- 1. Test SVS-0006, SVS-0097... in SVS but not in SValR
- 2. Test SVS-0014, SVS-0024 in SVaIR but not in SVS

TODO:

Modifs à faire dans SVaIR et SVS :

Test SVS-0014 in SVaIR but not in SVS: Indeed it appears that template for SVS test cases have an auto-increment macro enabled so when we deleted a test case during documents writing it has shifted several SVS number making SVS-0014 become SVS-0013. It is now fixed ans SVS-0014 is back. It will be available in the next release of the document. FAIT

Test SVS 0024 in SVaIR but not in SVS: I can see SVS 0024 at page 46 of the pdf. RIEN A FAIRE

- Test SVS-0006 in SVS but not in SVaIR:

Yes, maybe SVS-0006 test case should have been deleted from SVS because it is covered now by others test cases (see comments) : SVS-0059 and 0085.

But we kept it in SVS for traceability/history reasons... Maybe a little bit awkward, it will be removed from next releases.

- Test SVS-0097 in SVS but not in SVaIR:

Yes indeed, we forgot a requirement in SVaIR for R2: SSS-CP-FS-120/REQ-LFR-SRS-5212 which is validated by SVS-0097. It will be fixed in a new release. However, feature has been tested and is OK.

History

#1 - 19/11/2015 05:02 PM - bruno katra

- Description updated

#2 - 19/11/2015 05:03 PM - bruno katra

- Description updated
- Priority changed from Normal to High

#3 - 03/03/2016 05:01 PM - bruno katra

Done in SVaIR 1.1 and SVS 1.5

#4 - 03/03/2016 05:01 PM - bruno katra

- Status changed from In Progress to Closed
- % Done changed from 50 to 100

20/03/2024 1/1