

Doppler Logbook on ASDEX Upgrade - 2017October - # 4

2017October

2017-October 10

34666 Standard H mode, all 3 channels got signals, acquisition had remained =1s ->set to 7s

34667 W band, I signal seems saturated (or affected by high frequency noise). V band 1, also saturated?

test of different frequency pattern, load / save setup (bug with the Gage card, when the setup was prepared with 4 or 8 channels otherwise ok).

test of the correlation pattern, still some cross talk with the V band.

2017-October 6

2017-October 5