

## INSTRU - Issues

| #    | Tracker | Status  | Priority | Subject   | Assignee                | Updated             |
|------|---------|---------|----------|---|-------------------------|---------------------|
| 990  | Support | Closed  | Normal   | TC_LFR_LOAD_FILTER_PAR bugs   | bruno katra             | 22/03/2017 02:51 PM |
| 589  | Support | Closed  | Normal   | TC_LFR_LOAD_FBINS_MASK  | Veronique bouzid        | 03/03/2016 04:51 PM |
| 656  | Support | Closed  | Normal   | SHow to validate HK_LFR_VHDL_SM field   | Veronique bouzid        | 21/06/2018 01:27 PM |
| 545  | Support | Closed  | Normal   | Send TIMECODE without TC_LFR_UPDATE_TIME after SYNCHRONISATION                                | paul leroy              | 02/11/2015 11:18 AM |
| 634  | Support | Closed  | Urgent   | SEction HK_LFR_STATUS_WORD in TM_LFR_HK   | paul leroy              | 26/02/2016 11:35 AM |
| 537  | Support | Closed  | Urgent   | requirement SSS-CP-EQS-522 et SSS-CP-EQS-523  | Veronique bouzid        | 15/10/2015 12:57 PM |
| 473  | Support | Closed  | Normal   | R3 *** Adapter les scripts aux exigences  | Veronique bouzid        | 27/01/2017 02:41 PM |
| 868  | Support | Closed  | High     | Question sur merge_fbins_masks  | bruno katra             | 22/03/2017 02:57 PM |
| 3914 | Support | Stalled | Normal   | Question sur la dernière matrice des KCOEFF...  | Alexis Jeandet          | 08/12/2021 01:29 PM |
| 706  | Support | Closed  | Normal   | Pb aux bornes des intervalles pour le rejet des fréquences polluées par les roues inertielles | Gerald Saule            | 22/06/2018 05:22 PM |
| 714  | Support | Stalled | Normal   | Parametrage TCP   | Alexis Jeandet          | 22/03/2021 12:09 PM |
| 258  | Support | Closed  | Normal   | Numéro de version du code VHDL  | Jean-Christophe Pellion | 10/02/2015 04:27 PM |
| 561  | Support | Closed  | Normal   | Modifier le masque utilisé pour lire le time-code valide                                      | Veronique bouzid        | 22/02/2016 02:53 PM |
| 399  | Support | Closed  | Normal   | Mode Standby durant 3s à la fin des tests   | Veronique bouzid        | 01/10/2015 01:16 PM |
| 979  | Support | Closed  | Normal   | Mise à jour SRS et SVS et UM  | bruno katra             | 22/06/2018 05:15 PM |
| 596  | Support | Stalled | Normal   | Mise à jour logiciel LFR-SGSE   | Alexis Jeandet          | 22/03/2021 12:10 PM |
| 607  | Support | Closed  | Normal   | medium Criticity : How can we do it   | Veronique bouzid        | 18/01/2017 12:26 PM |
| 626  | Support | Closed  | Low      | Lost TM_LFR_HK in 3.0.0.22  | bruno katra             | 17/02/2016 01:42 PM |
| 721  | Support | Closed  | Low      | improvements in QCdf  | Alexis Jeandet          | 01/07/2016 11:12 AM |
| 181  | Support | Closed  | High     | Impossibilité de provoquer un TM_LFR_EXE_ERROR  | paul leroy              | 02/03/2016 02:44 PM |
| 956  | Support | Closed  | High     | Documenter le mecanisme associé à SSS-CP-EQS-526  | Alexis Jeandet          | 01/04/2019 12:03 PM |
| 627  | Support | Closed  | Urgent   | Commutation immediate   | Veronique bouzid        | 27/01/2017 02:36 PM |